CCR Impoundment Weekly Inspection

	35 ILL. /	ADM. Code 845 / 40	CFR Part 257	1 1 2
Station:	Kincaid		Date:	11/01/23
Impoundment Name:	Ash Pond	-	Time:	1:00'pm
IEPA Number:	W0218140002-01	-	Inspector(s):	D. Husan
Sky: CLOUDY Temp.:	52°F	Precip. (last 48 hrs):	0.00	Pool Elev.: - 16-0
ES" responses require description (the time of inspection. If "ACTION				ponse indicates no issues were observed n Safety Manager (DSM) . Attach

additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION		
					INVESTIGATE	SENT TO DSM	
CREST General Cond	dition:	Good	Fair / Poor Repairs: Date:				
Cracking		1			THE SECTION SECTION		
Settlement		V					
Erosion Rills		V					
Animal Burrows		1					
Misalignment		V					
Vegetation (greater than 12")		V_					
UPSTREAM EMBANKMENT General Cond	dition:	Good	Fair / Poor Repairs: Date:				
Cracking		7					
Sloughing / Bulging		V					
Seepage		N					
Sink Holes		V					
Animal Burrows		V					
Erosion Rills		N					
Slope Protection / Rip Rap		•					
Vegetation (greater than 12")							
DOWNSTREAM EMBANKMENT General Cond	dition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		7					
Sink Holes							
Sand Boils (indicate if flowing and color)		>	10.	/			
Animal Burrows			Financy / Hilling	V			
Erosion Rills		>	V				
Vegetation (greater than 12")		W					
SPILLWAY(S) General Cond	dition:	dood	Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)		V					
Obstructions Present		V					
Seepage		~					
Sand Boils (indicate if flowing and color)		V					
Erosion Rills		V					