CCR Impoundment Weekly Inspection

		ADM. Code 845 / 40 C		
Station:	Kincaid	ADIVI. Code 643 / 40 C	Date:	12/6/23
Impoundment Name:	Ash Pond	-	Time:	1:13 PM
IEPA Number:	W0218140002-01	_	Inspector(s):	1). Husun,
Sky: CLOUDY Temp.:	43°F	Precip. (last 48 hrs):	0.00"	Pool Elev.: 16.0
ES" responses require description (the time of inspection. If "ACTION Iditional sheets as necessary. Circle	" selected is "INVESTIGA	ATE", please indicate date f	PTION" section. "NO" responded via email to Dam	onse indicates no issues were observed a Safety Manager (DSM) . Attach
				ACTION

	rcle General Condition			ACTION		
ITEM	YES	NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO
CREST General	Condition:	Good	Fair / Poor Repairs: Date:			
Cracking		1				
Settlement		V				
Erosion Rills		V				
Animal Burrows		V				
Misalignment		1				
Vegetation (greater than 12")		1				
UPSTREAM EMBANKMENT General	Condition	Good	Fair / Poor Repairs: Date:			
Cracking		V				
Sloughing / Bulging		V				
Seepage		N				
Sink Holes		V				
Animal Burrows		N				
Erosion Rills		V				
Slope Protection / Rip Rap		V				
Vegetation (greater than 12")		1				
DOWNSTREAM EMBANKMENT General	Condition:	Good	/ Fair / Poor Repairs: Date:			
Cracking		V				
Sloughing / Bulging		V				
Seepage		V				
Sink Holes		~				
Sand Boils (indicate if flowing and color)		V		/		
Animal Burrows			MONITORING	V		
Erosion Rills		4	U			
Vegetation (greater than 12")		1				
SPILLWAY(S) General	Condition:	Good	Fair / Poor Repairs: Date:			
Actively Flowing (provide depth)		V	Additional and the second seco			
Obstructions Present		V				
Seepage		V				
Sand Boils (indicate if flowing and color)		1	1			
Erosion Rills		1				