CCR Impoundment Weekly Inspection

	35 ILL. A	DM. Code 845 / 40 CFR Part 257	1 1 1 0
Station:	Kincaid	Date:	12/13/23
Impoundment Name:	Ash Pond	Time:	10:00 AM
IEPA Number:	W0218140002-01	Inspector(s):	D. Huben
Sky: Suns Temp.:	37°F P	Precip. (last 48 hrs):	Pool Elev.:

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sheets as necessary. Circle deneral		NO			ACTION		
ITEM				MONITOR	INVESTIGATE	SENT TO DSM	
CREST General C	ondition:	Good	Fair / Poor Repairs: Date:				
Cracking		Y					
Settlement		V					
Erosion Rills		V					
Animal Burrows		V					
Misalignment		V					
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT General C	Condition:	Good	Fair / Poor Repairs: Date:				
Cracking		Y					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Animal Burrows		V					
Erosion Rills		V					
Slope Protection / Rip Rap		V					
Vegetation (greater than 12")		K			100000000000000000000000000000000000000		
DOWNSTREAM EMBANKMENT General C	Condition:	Good	Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and color)		V	1 16	/			
Animal Burrows	V	,	Finding Fizzing	V			
Erosion Rills		1					
Vegetation (greater than 12")		V					
SPILLWAY(S) General C	Condition	Good	Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)		V					
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)		V					
Erosion Rills		~					