CCR Impoundment Weekly Inspection

	35 ILL. A	ADM. Code 845 / 40	CFR Part 25/	, ,	
Station:	Kincaid		Date:	12/27/23	
Impoundment Name:	Ash Pond	-	Time:	0930	
IEPA Number:	W0218140002-01	-	Inspector(s):	1. Huber	
Sky: CLOUSY Temp.:	39°F F	Precip. (last 48 hrs):	0.00"	Pool Elev.:	-13"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sileets as flecessary. Circle General Co					ACTION		
ITEM		NO	DESCRIPTION		INVESTIGATE	SENT TO DSM	
CREST General Cor	dition/	Good	/ Fair / Poor Repairs: Date:				
Cracking		1					
Settlement		V					
Erosion Rills		V					
Animal Burrows		V					
Misalignment		V					
Vegetation (greater than 12")		1					
UPSTREAM EMBANKMENT General Cor	ndition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		1					
Seepage		V					
Sink Holes		V					
Animal Burrows		1					
Erosion Rills							
Slope Protection / Rip Rap							
Vegetation (greater than 12")		~					
DOWNSTREAM EMBANKMENT General Cor	ndition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and color)							
Animal Burrows			MONITORING	V			
Erosion Rills		V	V				
Vegetation (greater than 12")		·V					
	ndition:		/ Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)		V					
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)		V					
Erosion Rills		V					