CCR Impoundment Weekly Inspection 35 ILL, ADM, Code 845 / 40 CFR Part 257 Station: Kincaid Impoundment Name: Ash Pond IEPA Number: W0218140002-01 Inspector(s): Sky: Crouby Temp.: 36°F Precip. (last 48 hrs): 0.00 "YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section. **ACTION** MONITOR DESCRIPTION YES NO SENT TO DSM **ITEM** General Condition Good Fair / Poor Repairs: Date: CREST Cracking Settlement **Erosion Rills Animal Burrows** Misalignment Vegetation (greater than 12") Repairs: Date: V Cracking Sloughing / Bulging Seepage Sink Holes **Animal Burrows**

UPSTREAM EMBANKMENT | General Condition Good | Fair / Poor **Erosion Rills** Slope Protection / Rip Rap Vegetation (greater than 12") Date: DOWNSTREAM EMBANKMENT General Condition: Good / Fair / Poor Repairs: Cracking V Sloughing / Bulging Seepage Sink Holes Sand Boils (indicate if flowing and color) Animal Burrows **Erosion Rills** Vegetation (greater than 12") General Condition: 600d/ Fair / Poor SPILLWAY(S) Repairs: Date: Actively Flowing (provide depth) V **Obstructions Present** V Seepage Sand Boils (indicate if flowing and color) **Erosion Rills**