				\$ ³						
		CCF	R Im	poundment Week	y Inspection					
	3	35 IL	L. A	DM. Code 845 / 40	CFR Part 257		,			
Station: Kincaid					Date: 01/24/24					
Impoundment Name: Ash Pon			ond Time: 1:15, PM							
IEPA Number: W02181400			002-01 Inspector(s): 7. Hus							
Sky: Crousy Temp.: 410 K		Precip. (last 48 hrs):			1.36"	Pool	Pool Elev.:			
"YES" responses equire description at the time of inspection. If "ACTION additional sheets as necessary. Circle	I" selected is "IN	IVEST	ΓIGΑT	E", please indicate dat			DSM) .	Attach		
ITEM			NO	DESCRIPTION		ACTION				
		YES				MONITOR	INVESTIGATE	SENT TO DSM		
CREST	General Conditi	ion:	Good	/ Fair / Poor	Repairs:	Date:				
Cracking			V							
Settlement			V							
Erosion Rills			V							
Animal Burrows			V							
Misalignment			V							
Vegetation (greater than 12")			V							
UPSTREAM EMBANKMENT	General Conditi	ion:	Good	/ Fair / Poor	Repairs:	Date:				
Cracking			V							
Sloughing / Bulging			V							
Seepage			V							
Sink Holes			V							
Animal Burrows			V							
Erosion Rills			V						-	
Slope Protection / Rip Rap			V							
Vegetation (greater than 12")			V							
DOWNSTREAM EMBANKMENT	General Condit	ion: (dood	/ Fair / Poor	Repairs:	Date:	#20 4 54 61 11			
Cracking			V							
Sloughing / Bulging			V							
Seepage			V							

MUNITORKY

Repairs:

Date:

V

V

V

General Condition: Good / Fair / Poor

Sink Holes

Seepage

Erosion Rills

Animal Burrows Erosion Rills

Sand Boils (indicate if flowing and color)

Vegetation (greater than 12")
SPILLWAY(S)

Obstructions Present

Actively Flowing (provide depth)

Sand Boils (indicate if flowing and color)