CCR Impoundment Weekly Inspection

	33 ILL.	ADIVI. Code 645 / 40	J CI IX Fait 237	, /	
Statio	n: Kincaid		Date:	02/21/24	
Impoundment Nam	e: Ash Pond		Time:	12:15 PM	
IEPA Numbe	r: W0218140002-01	1	Inspector(s):	D. Huby	با
Sky: Pasy Temp	13° F	Precip. (last 48 hrs):	0.00"	Pool Elev	<u>- 9"</u>

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional streets as necessary. Girale General Sci					ACTION		
ITEM		NO	DESCRIPTION		INVESTIGATE	SENT TO DSM	
CREST General Co	ndition:	Good	Fair / Poor Repairs: Date:				
Cracking		V					
Settlement		V					
Erosion Rills		V			Section 15 (15 to 15		
Animal Burrows		V					
Misalignment		V					
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT General Co	ndition:	Good	Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Animal Burrows		V					
Erosion Rills		V					
Slope Protection / Rip Rap		V					
Vegetation (greater than 12")		X					
DOWNSTREAM EMBANKMENT General Co	ndition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and color)		V	A	/			
Animal Burrows		X	MONITORING	V			
Erosion Rills		V	MONITORING	X			
Vegetation (greater than 12")		Y	0				
SPILLWAY(S) General Co	ndition	Good	/ Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)		V					
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)		V					
Erosion Rills		V					