## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

		a *		100/24
Statio	n: Kincaid		Date:	02/28/24
Impoundment Nam	e: Ash Pond	DOM/DUMM	Time:	11:45 AM
IEPA Numbe	r: W0218140002-0	)1	Inspector(s):	D. Huzer
Sky: PCLOY Temp	: 28° F	Precip. (last 48 hrs):	0.00"	Pool Elev.:

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION			ACTION			
						MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Cor	dition:	Good	/ Fair / Poor	Repairs:	Date:		19		
Cracking		V							
Settlement		V							
Erosion Rills		V							
Animal Burrows		2							
Misalignment		V							
Vegetation (greater than 12")		V							
UPSTREAM EMBANKMENT   General Cor	dition:	Good	/ Fair / Poor	Repairs:	Date:				
Cracking		V							
Sloughing / Bulging		V							
Seepage		V							
Sink Holes		V							
Animal Burrows		V							
Erosion Rills		V							
Slope Protection / Rip Rap		V		×					
Vegetation (greater than 12")		K							
DOWNSTREAM EMBANKMENT   General Cor	ndition:	Good	/ Fair / Poor	Repairs:	Date:				
Cracking		V							
Sloughing / Bulging		V							
Seepage		V							
Sink Holes		V							
Sand Boils (indicate if flowing and color)		V				/			
Animal Burrows			MONITOR	Neg	-	V			
Erosion Rills		V		0					
Vegetation (greater than 12")		V							
SPILLWAY(S) General Cor	ndition:	Good	Fair / Poor	Repairs:	Date:				
Actively Flowing (provide depth)		V				10			
Obstructions Present		V	Service Servic	M. F. Harrison M. Harris					
Seepage		V							
Sand Boils (indicate if flowing and color)		V							
Erosion Rills		1							