CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

				A A			
Stati	on: Kincaid		Date:	03/15/24	15/24		
Impoundment Nar	me: Ash Pond		Time:	11:00 AM			
IEPA Numb	er: W0218140002	01	Inspector(s):	D. Hubul			
Sky: Crousy Tem	тр.: 46° F	Precip. (last 48 hrs):	1.26"	Pool Elev.:	-9"		

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

					ACTION			
ITEM		NO	DESCRIPTION		INVESTIGATE	SENT TO DSM		
CREST General Con	dition:	Good	Fair / Poor Repairs: Date:					
Cracking		V						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		K						
UPSTREAM EMBANKMENT General Con	dition:	Good	Fair / Poor Repairs: Date:					
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Animal Burrows		V						
Erosion Rills		V						
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")		1						
DOWNSTREAM EMBANKMENT General Con	dition:	Good	/ Fair / Poor Repairs: Date:					
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Sand Boils (indicate if flowing and color)		1						
Animal Burrows		V						
Erosion Rills			Monitoring	/				
Vegetation (greater than 12")		X	U					
	dition:	Good	Fair / Poor Repairs: Date:					
Actively Flowing (provide depth)		V						
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		V						