CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

		33 ILI	. ADIVI. Code 643 / 40		1 - 1 - 1	
Station:		Kincaid		Date:	03/20/24	
Impoundment Name:		Ash Pond	NO. OF THE PARTY O	Time:	11:15 AM	
IEPA Number:		W0218140002-0	01	Inspector(s):	D. Husen	
		. 170	The state of the s	(a () ()		- 900
Sky: (Lous L	Temp.:	91	Precip. (last 48 hrs):	0.00	Pool Elev.:	7.0

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO			ACTION			
			DESCRIPTION			INVESTIGATE	SENT TO DSM	
CREST General Co	ndition:	Good	Fair / Poor Repairs: Date:					
Cracking		1						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT General Co	ndition:	Good	Fair / Poor Repairs: Date:	4.1				
Cracking		1						
Sloughing / Bulging		V						
Seepage		1						
Sink Holes		V						
Animal Burrows		V						
Erosion Rills		V						
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")		V						
DOWNSTREAM EMBANKMENT General Co	ndition:	Good	Fair / Poor Repairs: Date:					
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Sand Boils (indicate if flowing and color)		1						
Animal Burrows		V	A		,			
Erosion Rills			Monitoning		V			
Vegetation (greater than 12")		V						
	ndition:	Good	Fair / Poor Repairs: Date:					
Actively Flowing (provide depth)		7						
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		1						