## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

		00 144	in reprint course in f		. 1	*
Station:		Kincaid		Date:	05/01/2	. 4
Impoundment Name:		Ash Pond	- Control of the Cont	Time:	11:45 AV	4
IEPA Number:		W0218140002-01		Inspector(s):	D. Huse	r
	Town	730 F	Precip. (last 48 hrs):	0 00"	Pool F	lev.: - 9.0"
Sky: Crousy	Temp.:	10 1	Precip. (last 46 lirs).		1001 E	1CV11

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION			
					MONITOR	INVESTIGATE	SENT TO DSM	
CREST Ger	neral Condition:	Good	Fair / Poor Repairs: Date:					
Cracking		V						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT Ger	neral Condition:	Good	Fair / Poor Repairs: Date:	A CONTRACTOR AND AND				
Cracking		V						
Sloughing / Bulging		V						
Seepage		/						
Sink Holes		V						
Animal Burrows		V						
Erosion Rills		V						
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")		V						
DOWNSTREAM EMBANKMENT Ger	neral Condition:	Good	Fair / Poor Repairs: Date:					
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Sand Boils (indicate if flowing and color)		V						
Animal Burrows			Monitoning		V			
Erosion Rills		V	U					
Vegetation (greater than 12")		V	*					
SPILLWAY(S) Ger	neral Condition	Good	Fair / Poor Repairs: Date:					
Actively Flowing (provide depth)		V						
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		V						