## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	33 IEE.	ADIVI. COGC 045 / 40	611110111011	1.0/04	
Station:	Kincaid		Date:	05/22/24	
Impoundment Name:	Ash Pond	NAMES OF	Time:	1:00 PM	
			Inspector(s):	D. Hwyyl	
Sky: Pany Temp.:	14° K	Precip. (last 48 hrs):	0.50"	Pool Elev.:	-13"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

additional sheets as necessary. Circle deneral con		NO	DESCRIPTION	ACTION		
ITEM				MONITOR	INVESTIGATE	SENT TO DSM
CREST General Con	dition:	Good	/ Fair / Poor Repairs: Date:			e de la companya de l
Cracking		V		) + /···		
Settlement		V				
Erosion Rills		V				*
Animal Burrows		1				
Misalignment		V				
Vegetation (greater than 12")		1				रक्षा सुप्रस
UPSTREAM EMBANKMENT General Con	dition:	Good	Fair/Poor Repairs Date:			
Cracking		V				
Sloughing / Bulging		V				
Seepage		1/				
Sink Holes		V				
Animal Burrows		1				-
Erosion Rills		1			<u> </u>	
Slope Protection / Rip Rap		1			<u> </u>	
Vegetation (greater than 12")		V		K 950.1.1		18422000
DOWNSTREAM EMBANKMENT General Con	idition:		Fair / Poor Repairs: Date:			-
Cracking		V				
Sloughing / Bulging		N				
Seepage		V		ļ		
Sink Holes		V		<u> </u>		ļ
Sand Boils (indicate if flowing and color)		N			<u> </u>	<u> </u>
Animal Burrows	1		MONITONING	V	<u> </u>	
Erosion Rills		V,	0		ļ	
Vegetation (greater than 12")		12		ļ		
SPILLWAY(S) General Cor	ndition	Good	/ Fair / Poor Répairs: Date:			
Actively Flowing (provide depth)		V,		ļ		
Obstructions Present		V				
Seepage		V				
Sand Boils (indicate if flowing and color)		V				<u> </u>
Erosion Rills		V				