CCR Impoundment Weekly Inspection 35 III ADM. Code 845 / 40 CFR Part 257

	JJ 11-41	DIVIT COUC C-10 / 10 CITIC CITIC	
. Station:	Kincaid	Date	: 05/29/24
Impoundment Name:	Ash Pond	Time	: 1:15 PM
	W0218140002-01	Inspector(s): D. Huber
Sky: P CUSY Temp.:	71°F	Precip. (last 48 hrs): 0.05"	Pool Elev.: - 12 "

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach

additional sheets as necessary. Circle General Condition for each section. **ACTION** MONITOR YES NO DESCRIPTION ITEM SENT TO DSM General Condition, Good) Fair / Poor CREST Repairs: Date: Cracking Settlement **Erosion Rills Animal Burrows** Misalignment Vegetation (greater than 12") UPSTREAM EMBANKMENT General Condition Good Fair / Poor Date: Repairs: Cracking Sloughing / Bulging Seepage Sink Holes **Animal Burrows** V **Erosion Rills** V Slope Protection / Rip Rap Vegetation (greater than 12") DOWNSTREAM EMBANKMENT General Condition Good / Fair / Poor Repairs: Cracking V Sloughing / Bulging Seepage Sink Holes Sand Boils (indicate if flowing and color) MONITORING **Animal Burrows Erosion Rills** Mowing Vegetation (greater than 12") SPIELWAY(S) General Condition Good / Fair / Poor Date: ď Actively Flowing (provide depth) **Obstructions Present** v Seepage Sand Boils (indicate if flowing and color) **Erosion Rills**