## CCR Impoundment Weekly Inspection

	35 ILL	ADM. Code 845 / 40	CFR Part 257		
Station:	Kincaid		Date:	06/05/24	_
Impoundment Name:	Ash Pond	,	Time:	1300	_
IEPA Number:		01	Inspector(s):	D. 19 worn	
Sky: Pag Temp.:	TOF.	Precip. (last 48 hrs):	0.6"	Pool Elev.	: -12"
"YES" responses require description at the time of inspection. If "ACTION additional sheets as necessary. Circle	I" selected is "INVESTI	GATE", please indicate date	RIPTION" section. "NO" res forwarded via email to Dan	ponse indicates no issues n Safety Manager (DSM)	were observed . Attach
					A CTLOBI

ado ACTION MONITOR ITEM YES NO DESCRIPTION SENT TO DSM General Condition/Good/Fair/Poor CREST Repairs: Date: Cracking Settlement **Erosion Rills** Animal Burrows Misalignment Vegetation (greater than 12") UPSTREAM EMBANKMENT General Condition: (5000) Fair / Poor Repairs: Date: Cracking V 1 Sloughing / Bulging Seepage Sink Holes **Animal Burrows** 1 V **Erosion Rills** Slope Protection / Rip Rap Mowing In mobiless Vegetation (greater than 12") DOWNSTREAM EMBANKMENT General Condition: 6000 / Fair / Poor Date: Cracking Sloughing / Bulging Seepage Sink Holes Sand Boils (indicate if flowing and color) V **Animal Burrows Erosion Rills** IN Brogness Vegetation (greater than 12") / Fair / Poor SPILLWAY(S) General Condition: Good Actively Flowing (provide depth) **Obstructions Present** ~ Seepage Sand Boils (indicate if flowing and color) **Erosion Rills**