## CCR Impoundment Weekly Inspection 🛫 25 III ADM Code 845 / 40 CER Part 257

	22 ITT	. ADM. Code 643 / 40	CFN Part 237	, ,	
Station	Kincaid		Date: _{	06/19/24	
Impoundment Name	: Ash Pond		Time:	1300	
IEPA Number	: W0218140002-0	01	Inspector(s):		
Sky: CLEAR_ Temp.	: 89°F	Precip. (last 48 hrs):	0.00"	Pool Elev.:	7

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach

additional sheets as necessary. Circle General Cor	additional sheets as necessary. Circle General Condition for each section.										
	YES	NO	DESCRIPTION	ACTION							
ITEM				MONITOR	INVESTIGATE	SENT TO DSM					
CREST General Con-	dition:	Good	/Fair / Poor Repairs Date:		74- 1						
Cracking		7									
Settlement		V									
Erosion Rills		V			<u></u>						
Animal Burrows		V									
Misalignment		V									
Vegetation (greater than 12")		V									
UPSTREAM EMBANKMENT General Con	dition:	<b>G</b> ood	/ Fair / Poor Repairs: Date:								
Cracking		1									
Sloughing / Bulging		V									
Seepage		1									
Sink Holes		1									
Animal Burrows		1		,							
Erosion Rills		/									
Slope Protection / Rip Rap		V	•								
Vegetation (greater than 12")		X									
DOWNSTREAM EMBANKMENT General Con	dition:	Gogli	/ Fair / Poor Repairs: Date:								
Cracking		<b>V</b>									
Sloughing / Bulging		V									
Seepage		V									
Sink Holes		V									
Sand Boils (indicate if flowing and color)					X						
Animal Burrows	V		MONITONING	V							
Erosion Rills		~									
Vegetation (greater than 12")		人									
	dition:	600)	/ Fair / Poor Repairs: Date:								
Actively Flowing (provide depth)		V									
Obstructions Present		V			,						
Seepage		V									
Sand Boils (indicate if flowing and color)		V									
Erosion Rills		V									