CCR Impoundment Weekly Inspection

Station: Kincaid Date: 07 10 24
Impoundment Name: Ash Pond Time: 12:00 PM
IEPA Number: W0218140002-01 Inspector(s): 7 Hubsun

Sky: Cround Temp.: 82 Precip. (last 48 hrs): 2.69 Pool Elev.: 10

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach

additional sheets as necessary. Circle General Con		NO	DESCRIPTION	ACTION		
				MONITOR	INVESTIGATE	SENT TO DSM
CREST General Con	ditlon (Good	Fair / Poor Repairs Date:		A STATE	
Cracking		V				
Settlement		V				
Erosion Rills		V				
Animal Burrows		V				<u> </u>
Misalignment		V				
Vegetation (greater than 12")		V				<u> </u>
UPSTREAM EMBANKMENT General Cor	dition	Good	Fair / Poor Repairs: Date:			
Cracking		V			ļ	
Sloughing / Bulging		V				
Seepage		V				
Sink Holes		V				
Animal Burrows		1				
Erosion Rills		1				
Slope Protection / Rip Rap	-	1				
Vegetation (greater than 12")		1				
DOWNSTREAM EMBANKMENT General Cor	dition:	bood	Fair / Poor Repairs Date:			
Cracking		V				_
Sloughing / Bulging		V				
Seepage		V				
Sink Holes		1				
Sand Boils (indicate if flowing and color)		V			-	
Animal Burrows	1		MONITORING	1		
Erosion Rills		1	V		-	
Vegetation (greater than 12")		V				
SPILLWAY(S) General Cor	iditlon:		Fair / Poor Repairs: Date:			
Actively Flowing (provide depth)		V				
Obstructions Present		V				
Seepage		V				
Sand Boils (indicate if flowing and color)		V				
Erosion Rills		V				