CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid	Dat	e: 0	8/07/	24	
Impoundment Name:	Ash Pond	Tim		1:00 P	14	
IEPA Number:	W0218140002-01	Inspector(. Hul	rue	
Sky: CLEAR Temp.:	B5°F	recip. (last 48 hrs):	· ·	Pool	Elev.: -14.0	را ا

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

, controlled and a second a second and a second a second and a second a second and a second and a second and				ACTION			
ITEM	YES	NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Cor	ndition;	Good	/ Fair / Poor Repairs: Date:	r A. S. S. V. Št. Lestadi		The second	
Cracking		V					
Settlement	***************************************	V					
Erosion Rills		V					
Animal Burrows		V			<u> </u>		
Misalignment		V					
Vegetation (greater than 12")		Z					
UPSTREAM EMBANKMENT General Cor	ndition:	Good	/ Fair / Poor Repairs: Date:			(A. 75)	
Cracking		V	1		"····		
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Animal Burrows		V				<u> </u>	
Erosion Rills		~				-	
Slope Protection / Rip Rap		ν.					
Vegetation (greater than 12")		V					
DOWNSTREAM EMBANKMENT General Cor	idition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and color)	,	V					
Animal Burrows	V						
Erosion Rills		V					
Vegetation (greater than 12")		V					
SPILLWAY(S) General Cor	idition:	Good	/ Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)		V					
Obstructions Present		V					
Seepage		V					
Sand Boils (Indicate if flowing and color)		V					
Erosion Rills		V					