CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

		,				
Station:	Kincaid	_	Date:	08/21	124	
Impoundment Name:	Ash Pond	_	Time:			
IEPA Number:	W0218140002-01	_	Inspector(s):	D. Hub	in	
Sky: P CLOY Temp.:	73°F	Precip. (last 48 hrs):	0.00	Po	ool Elev.:	.0"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION		
					INVESTIGATE	SENT TO DSM	
CREST General Cor	dition:	6000	Fair / Poor Repairs: Date:		eteny gyt in		
Cracking		5					
Settlement		V					
Erosion Rills		V					
Animal Burrows		1				langer on a control	
Misalignment		V					
Vegetation (greater than 12")		X					
UPSTREAM EMBANKMENT General Cor	dition	Good	Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Animal Burrows		V					
Erosion Rills		V					
Slope Protection / Rip Rap		~					
Vegetation (greater than 12")		V					
DOWNSTREAM EMBANKMENT General Cor	dition:	800d	/ Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and color)		V		/			
Animal Burrows			Monitoring	V			
Erosion Rills		V	0				
Vegetation (greater than 12")		V					
SPILLWAY(S) General Cor	dition:	Good	Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)	T	V					
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)		-					
Erosion Rills		V					