CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

| • | 33 166 | ADM COGC 043 / 40 | o ci it i di c 25, | 1-0 201 |
|-------------------|---------------|------------------------|--------------------|-------------------|
| Station: | Kincaid | | Date: | 08/28/24 |
| Impoundment Name: | Ash Pond | | Time: | 10:30 AM |
| IEPA Number: | W0218140002-0 | <u>L</u> | Inspector(s): | HUSEN/HALLETI |
| Sky: <u> </u> | 73°F | Precip. (last 48 hrs): | 0.05" | Pool Elev.: -14.0 |

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

| | | | : | | ACTION | | |
|--|----------|------|------------------------------|------------|---|----------------|--|
| ITEM | | NO | DESCRIPTION | | INVESTIGATE | SENT TO DSM | |
| CREST General Cor | idition: | Good | Fair / Poor Repairs: Date: | \$255 E.S. | A. W. Str. | (S. %) | |
| Cracking | | V | | | | | |
| Settlement | | V | | | | | |
| Erosion Rills | | V | · | | | | |
| Animal Burrows | | V | | | | | |
| Misalignment | | V | | | | | |
| Vegetation (greater than 12") | | V | | | | | |
| UPSTREAM EMBANKMENT General Cor | idition | Good | Fair / Poor Repairs: Date: | | | i di dise | |
| Cracking | | V | | | | | |
| Sloughing / Bulging | | V | | | | | |
| Seepage | | V | · | | | | |
| Sink Holes | | V | | | | | |
| Animal Burrows | | V | | | | | |
| Erosion Rills | | V | | | | | |
| Slope Protection / Rip Rap | | V | | | | | |
| Vegetation (greater than 12") | | 1 | | | | | |
| DOWNSTREAM EMBANKMENT General Con | dition: | Good | Fair / Poor Repairs: Date: | | | | |
| Cracking | | V | | | | | |
| Sloughing / Bulging | | V | | | | | |
| Seepage | | V | | | | | |
| Sink Holes | | V | | | | | |
| Sand Boils (indicate if flowing and color) | | V | | | | | |
| Animal Burrows | V | V | MONITONINZ | V | | | |
| Erosion Rills | | 1 | V | | | | |
| Vegetation (greater than 12") | | V | | | | | |
| SPILLWAY(S) General Con | dition: | Good | / Fair / Poor Repairs: Date: | | | | |
| Actively Flowing (provide depth) | | V | | | | | |
| Obstructions Present | | V | | | | | |
| Seepage | | V | | | *************************************** | | |
| Sand Boils (indicate if flowing and color) | | V | | | | | |
| Erosion Rills | | V | | | | | |