CCR Impoundment Weekly Inspection 35 III ADM. Code 845 / 40 CFR Part 257

	33 166	ADIVI. COUE 843 / 40	CFR Fait 237	///	
Station:	Kincaid		Date:	09/11/24	
Impoundment Name:	Ash Pond		Time:	12.PM	
IEPA Number:	W0218140002-0	1	Inspector(s);	D. Hubur	
Sky: CLOUSY Temp.:	80° F	Precip. (last 48 hrs):	0.00"	Pool Elev.:	-16"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. if "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	·	ACTION		
			DESCRIPTION		INVESTIGATE	SENT TO DSM
CREST General Con	dition;	Good	Fair / Poor Repairs: Date:	5 2		747 (3)
Cracking		V				
Settlement		/				
Erosion Rills		1				
Animal Burrows		V				
Misalignment		V				
Vegetation (greater than 12")		1				
UPSTREAM EMBANKMENT General Con	dition:	Good	/ Fair / Poor Repairs: Date:		en Valorite	TV ST LV COVENE
Cracking		V				
Sloughing / Bulging						
Seepage		V				
Sink Holes		1				
Animal Burrows		V				
Erosion Rills		V				
Slope Protection / Rip Rap		V				
Vegetation (greater than 12")		区				
DOWNSTREAM EMBANKMENT General Con	dition:	Good	/ Fair / Poor Repairs: Date:		. 77.7	
Cracking		V				
Sloughing / Bulging		V				
Seepage		~ .				
Sink Holes		7				
Sand Boils (indicate if flowing and color)	,	v				
Animal Burrows	V		MONITORING	1		
Erosion Rills		V				
Vegetation (greater than 12")		V				
SPILLWAY(S) General Con	dition:	Good	/ Fair / Poor Repairs: Date:			A STATE
Actively Flowing (provide depth)		V				
Obstructions Present	1	V				
Seepage		1				
Sand Boils (Indicate if flowing and color)		V				
Erosion Rills	1	V				