CCR Impoundment Weekly Inspection 35 ILL ADM, Code 845 / 40 CFR Part 257

	مر بين دد	Wit Code 043 / 40 CFR Fait 23/	, 1
Station:	Kincaid	Date	10/02/24
Impoundment Name:	Ash Pond	Time:	11:00 Alb
	W0218140002-01	Inspector(s):	D. Huben
		1.	

Sky: PCLOY Temp.: 65°F Precip. (last 48 hrs): 0.00" Pool Elev.: -14"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

			NO DESCRIPTION	ACTION		
ITEM	YES	NO		MONITOR	INVESTIGATE	SENT TO
CREȘT General Cor	dition	Good	/Fair / Poor Repairs: Date:		- EXTE	100
Cracking		7				
Settlement		V				
Erosion Rills		V				
Animal Burrows		V				
Misalignment		V.				
Vegetation (greater than 12")	1	1/				ļ
UPSTREAM EMBANKMENT General Con	idition:	Good	Fair / Poor Repairs: Date:			
Cracking		V				
Sloughing / Bulging		V				├─
Seepage	1	1				
Sink Holes		V				<u> </u>
Animal Burrows		V			**************************************	
Erosion Rills		V			**************************************	ļ
Slope Protection / Rip Rap		ν			i 	
Vegetation (greater than 12")	†	V				
DOWNSTREAM EMBANKMENT General Con	dition:	Good	Fair/Poor Repairs: Date:	5524		N 17 2 2
Cracking	21 March 9, 201, 1970	V		jurio (6)		
Sloughing / Bulging	†	1/				
Seepage		V				
Sink Holes	1	V				
Sand Boils (indicate if flowing and color)	3.00	マ				
Animal Burrows	V		MONITORING	V		
Erosion Rills	1-	V	7.70,0,7,0	V	+	<u> </u>
Vegetation (greater than 12")		V				
SPILLWAY(S) General Con-	dition: (Fair / Poor Répairs: Date:			
Actively Flowing (provide depth)		V	Copyrion Date			18/30 ⁰
Obstructions Present		V			•	
Seepage	1	V	,	·		
Sand Boils (indicate if flowing and color)	+-+	7				
Erosion Rills	1	V				