CCR Impoundment Weekly Inspection 35 III. ADM. Code 845 / 40 CFR Part 257

	33 1221 712	in code of 7 to critical 257	1 1 1	
Station:	Kincaid	Date:	11/06/24	
Impoundment Name:	Ash Pond	Time:	1:30 PM	
IEPA Number:	W0218140002-01	Inspector(s):	D. Huber	
		n.		F1

Sky: CLOUNY Temp.: 63° F Precip. (last 48 hrs): 3.65" Pool Elev.: -13.0

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

		NO	DESCRIPTION		ACTION		
ITEM	YES				MONITOR	INVESTIGATE	SENT TO DSM
CREST General Co	ndition:	Good	Fair / Poor Repairs:	Date:			
Cracking		1					
Settlement		V					
Erosion Rills		V					
Animal Burrows		V					
Misalignment		V					
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT General Co	ndition:	Good	/ Fair / Poor Repairs:	Date:			
Cracking		V					
Sloughing / Bulging		~					
Seepage		/					
Sink Holes		V					
Animal Burrows		V					
Erosion Rills		V					
Slope Protection / Rip Rap		V					
Vegetation (greater than 12")		V					
DOWNSTREAM EMBANKMENT General Co	ndition:	Good	/ Fair / Poor Repairs:	Date:		1	
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and color)		1					
Animal Burrows	V		MONITORINO		V		
Erosion Rills		V	-				
Vegetation (greater than 12")		V		7			
	ndition:	Good	/ Fair / Poor Repairs:	Date:			
Actively Flowing (provide depth)		V		and and any analysis of the second and an area of the second and any and a second and any of the second and any			
Obstructions Present		V					1
Seepage		V					
Sand Boils (indicate if flowing and color)		V					1
Erosion Rills		V					T