CCR Impoundment Weekly Inspection

	35 ILL. /	ADM. Code 845 / 40	0 CFR Part 257	1 1
Station:	Kincaid		Date:	11/20/24
Impoundment Name:	Ash Pond		Time:	
IEPA Number:	W0218140002-01		Inspector(s):	D. Huben
ky: P CLSL Temp.:	62°F	Precip. (last 48 hrs):	0.06	Pool Elev.:

additional sheets as necessary. Circle General Condition for each section.

Sky: PCLDY "YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach

	General Condition	Γ			ACTION		
ITEM	YES N		DESCRIPTION		INVESTIGATE	SENT TO DSM	
CREST General Co	ndition;	Good	Fair / Poor Repairs: Date:				
Cracking		V					
Settlement		V					
Erosion Rills		1					
Animal Burrows		V					
Misalignment		V					
Vegetation (greater than 12")		V					
UPSTREAM EMBANKMENT General Co	ndition;	Good	Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Animal Burrows		V					
Erosion Rills		V					
Slope Protection / Rip Rap		V					
Vegetation (greater than 12")		V					
DOWNSTREAM EMBANKMENT General Co	ndition:	Good	Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and color)		V					
Animal Burrows	V		MONITORING				
Erosion Rills		V	U				
Vegetation (greater than 12")		V					
SPILLWAY(S) General Co	ndition:	Good	Fair / Poor Repairs: Date:			A COLUMN	
Actively Flowing (provide depth)		V	AND THE RESIDENCE OF THE PROPERTY OF THE PROPE				
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)		V					
Erosion Rills		V					