## CCR Impoundment Weekly Inspection

35 ILL. ADM. Code 845 / 40 CFR Part 257 Station: Kincaid Impoundment Name: Ash Pond Time: IEPA Number: W0218140002-01 Inspector(s): 0.00

Precip. (last 48 hrs):

Temp.:

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION	ACTION		
	YES			MONITOR	INVESTIGATE	SENT TO DSM
GREST General Con	dition:	Good	Fair / Poor Repairs: Date:	N. N. J.		
Cracking		7				
Settlement		V		************		
Erosion Rills		V				
Animal Burrows		<b>V</b>				
Misalignment		<b>V</b>				
Vegetation (greater than 12")		7				
UPSTREAM EMBANKMENT General Con-	dition:	Good	Y Fair / Poor Repairs: Date:	14 .4.7 3. 2483		
Cracking		V				
Sloughing / Bulging		1				
Seepage		١				
Sink Holes		7	1			
Animal Burrows	<b>√</b>		Monstoning	V		
Erosion Rills		1				-
Slope Protection / Rip Rap		1				
Vegetation (greater than 12")		1				
DOWNSTREAM EMBANKMENT General Con-	dition:	Good	Fair / Poor Repairs: Date:			
Cracking		7				
Sloughing / Bulging		V				
Seepage		~				
Sink Holes		V				
Sand Boils (indicate if flowing and color)		~				
Animal Burrows		V				
Erosion Rills		V				
Vegetation (greater than 12")		Y				
SPILLWAY(S) General Cond	lition:	Good	Fair / Poor Repairs: Date:			2.1
Actively Flowing (provide depth)		7				
Obstructions Present		V				
Seepage		1				
Sand Boils (indicate if flowing and color)		_ / I				
Erosion Rills		7				