CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	00.11		0 0111 CIT C III C		
Statio	n: Kincaid		Date:	12/11/24	
Impoundment Name	e: Ash Pond		Time:	11:10 AM	
IEPA Numbe	r: W0218140002-01		Inspector(s):	D. Huber	
Sky: <u>Clousy</u> Temp	.: 36° F	Precip. (last 48 hrs):	0.00"	Pool Elev.:	-6.0"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION		
					INVESTIGATE	SENT TO DSM	
CREST General Con	dition	Good	Fair / Poor Repairs: Date:		The same		
Cracking		1			STATISTICAL GUIS		
Settlement		1					
Erosion Rills		V					
Animal Burrows		/					
Misalignment		V					
Vegetation (greater than 12")		1					
UPSTREAM EMBANKMENT General Con-	dition:	Gòog	/ Fair / Poor Repairs: Date:				
Cracking	-	1		and the last of th	CHARLES AND		
Sloughing / Bulging		V	3		_		
Seepage		V					
Sink Holes		M					
Animal Burrows		1	,				
Erosion Rills		V					
Slope Protection / Rip Rap		~					
Vegetation (greater than 12")		10					
DOWNSTREAM EMBANKMENT General Con-	dition	Good	/ Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		V					
Seepage		V					
Sink Holes		1					
Sand Boils (indicate if flowing and color)		V	1				
Animal Burrows			Monstoning	~			
Erosion Rills		V					
Vegetation (greater than 12")		1					
SPILLWAY(S) General Con-	dition:	Good	Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)		7		-	NA HAWADARA		
Obstructions Present		V					
Seepage		V					
Sand Boils (indicate if flowing and color)		V					
Erosion Rills		V					