CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid			Date:				
Impoundment Name: Ash Por				Time:	1100			
IEPA Number:	mber: W021814000		•		D. Tim Amol	1		
Sky: Rt wasy Temp.:	44F	Р	recip. (last 48 hrs):	0"	Pool -	Elev.:	-12	
"YES" responses require description (served
at the time of inspection. If "ACTION additional sheets as necessary. Circle				e forwarded via email to Da	m Salety Manager (, (ועוכע	Attach	
						ACTION		
ITEM	YES	NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		/						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT	General Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking	-	/						
Sloughing / Bulging		V						
Seepage		1						
Sink Holes		V						
Animal Burrows		V						
Erosion Rills		V						
Slope Protection / Rip Rap	x.	V	=					
Vegetation (greater than 12")		/						
DOWNSTREAM EMBANKMENT	General Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		/	0 25					
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Sand Boils (indicate if flowing	and color)	/						
Animal Burrows		/					1	
Erosion Rills		/						
Vegetation (greater than 12")		V						
SPILLWAY(S)	General Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide de	pth)	MA						
Obstructions Present		V						
Seepage		1						
Sand Boils (indicate if flowing	and color)	V						
Erosion Rills		V						