•				poundment Week DM. Code 845 / 40	•		م د ا	•	
Station:	Kincaid				D	ate: 01/08/	23	_	
Impoundment Name: Ash P		ond			Ti	me: // 30 A	<u>M</u>	_	
IEPA Number:	W0218140002-01			•	Inspector(s): D. Hwyur				
Sky: Coust Temp.:	22°	F	P	recip. (last 48 hrs):	0.0 "	Pool	Elev.:	-10	2"
"YES" responses require description (at the time of inspection. If "ACTION additional sheets as necessary. Circle	" selected is "	INVES	TIGAT	E", please indicate dat					
							ACTION		
ITEM		YES	NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Cond	lition:	Good	Fair / Poor	Repairs:	Date:			
Cracking)\ 						
Settlement			>						
Erosion Rills			V						
Animal Burrows			1			:			
Misalignment			\						
Vegetation (greater than 12")			×						
UPSTREAM EMBANKMENT	General Cond	lition:	Good	Fair / Poor	Repairs:	Date:			
Cracking)>	-					
Sloughing / Bulging			\						
Seepage			V						
Sink Holes			V						
Animal Burrows			1					<u> </u>	
Erosion Rills			~						
Slope Protection / Rip Rap			₩,						
Vegetation (greater than 12")			V						
DOWNSTREAM EMBANKMENT	General Cond	lition:(Good	/ Fair / Poor	Repairs:	Date:	-		

7

V

V

シ

7

マ

V

General Condition: Good / Fair / Poor

MONTONING

Repairs:

Date:

Cracking

Seepage Sink Holes

Sloughing / Bulging

Animal Burrows

Erosion Rills

Seepage

Erosion Rills

Sand Boils (indicate if flowing and color)

Vegetation (greater than 12")
SPILLWAY(S)

Obstructions Present

Actively Flowing (provide depth)

Sand Boils (indicate if flowing and color)