## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

| Station:          |     | Kincaid     |                        | Date:         |             |       |
|-------------------|-----|-------------|------------------------|---------------|-------------|-------|
| Impoundment Name: |     | Ash Pond    |                        | Time:         |             |       |
| IEPA Number:      |     | 0218140002- | 01                     | Inspector(s): | 1). Hwom    | 3     |
| Sky: County Tem   | o.: | 18° F       | Precip. (last 48 hrs): | 6.00"         | Pool Elev.: | -9.0" |

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

| ITEM                                       |         |      |                              |              | ACTION   |                |  |
|--|---------|------|------------------------------|--------------|--|----------------|--|
|  |         | NO ( | DESCRIPTION                  | MONITOR      | INVESTIGATE  | SENT TO<br>DSM |  |
| CREST General Cond                         | dition  | Good | Fair / Poor Repairs: Date:   |              |  |                |  |
| Cracking                                   |         | V    |                              |              |  |                |  |
| Settlement                                 |         | ~    |                              |              |  |                |  |
| Erosion Rills                              |         | V    |                              |              |  |                |  |
| Animal Burrows                             |         | V    |                              |              |  |                |  |
| Misalignment                               |         | ~    |                              |              |  |                |  |
| Vegetation (greater than 12")              |         | X    |                              |              |  |                |  |
| UPSTREAM EMBANKMENT General Cond           | dition: | Good | Fair / Poor Repairs: Date:   |              |  |                |  |
| Cracking                                   |         | 9    |                              | AND SHEETING |  |                |  |
| Sloughing / Bulging                        |         | V    |                              |              |  |                |  |
| Seepage                                    |         | V    | s                            |              |  |                |  |
| Sink Holes                                 |         | V    |                              |              |  |                |  |
| Animal Burrows                             |         | /    |                              |              |  |                |  |
| Erosion Rills                              |         | 1    |                              |              |  |                |  |
| Slope Protection / Rip Rap                 |         | 1    |                              |              |  |                |  |
| Vegetation (greater than 12")              |         | 1    |                              |              |  |                |  |
| DOWNSTREAM EMBANKMENT General Cond         |         | Good | / Fair / Poor Repairs: Date: |              |  |                |  |
| Cracking                                   |         | V    | ·                            |              |  |                |  |
| Sloughing / Bulging                        |         | /    |                              |              |  |                |  |
| Seepage                                    |         | V    |                              |              |  |                |  |
| Sink Holes                                 |         | /    |                              |              |  |                |  |
| Sand Boils (indicate if flowing and color) |         | /    |                              | /            |  |                |  |
| Animal Burrows                             |         |      | Montoning                    | V            |  |                |  |
| Erosion Rills                              |         | V    | •                            |              |  |                |  |
| Vegetation (greater than 12")              |         | 1    |                              |              |  |                |  |
| SPILLWAY(S) General Cond                   | dition: | Good | Fair / Poor Repairs: Date:   |              |  |                |  |
| Actively Flowing (provide depth)           |         | 7    |                              |              | STATE OF THE PARTY |                |  |
| Obstructions Present                       |         | V    |                              |              |  |                |  |
| Seepage                                    |         | V    |                              |              |  |                |  |
| Sand Boils (indicate if flowing and color) |         | V    |                              |              |  |                |  |
| Erosion Rills                              |         | V    |                              |              |  |                |  |