CCR Impoundment Weekly Inspection R5 III. ADM. Code 845 / 40 CFR Part 257

	35 ILL.	ADIVI. Code 845 / 40		1 1 -	
Station:	Kincaid		Date:	01/22/25	
Impoundment Name:	Ash Pond		Time:	1:30 PM	
IEPA Number:	W0218140002-0	<u> </u>	Inspector(s):	D. Hubun	
Sky: <u>Crowsy</u> Temp.:	5° F	Precip. (last 48 hrs):	0.00	Pool Elev.:	-7.0°

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM		NO	DESCRIPTION		ACTION		
					INVESTIGATE	SENT TO DSM	
CREST General Cond	lition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		V					
Settlement		V					
Erosion Rills		~					
Animal Burrows		V					
Misalignment		V					
Vegetation (greater than 12")		V			•		
UPSTREAM EMBANKMENT General Cond	lition:	(coo)	/ Fair / Poor Repairs: Date:				
Cracking		~					
Sloughing / Bulging		√		·			
Seepage		V					
Sink Holes		~					
Animal Burrows		V					
Erosion Rills		1					
Slope Protection / Rip Rap		V		·			
Vegetation (greater than 12")		7					
DOWNSTREAM EMBANKMENT General Cond	lition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		V					
Sloughing / Bulging		1					
Seepage		V					
Sink Holes		V					
Sand Boils (indicate if flowing and color)		~		,			
Animal Burrows			MONITORING	V			
Erosion Rills		V					
Vegetation (greater than 12")		7					
SPILLWAY(S) General Cond	lition:	dood	/ Fair / Poor Repairs: Date:			1 1	
Actively Flowing (provide depth)		7					
Obstructions Present		V					
Seepage		7					
Sand Boils (indicate if flowing and color)		7					
Erosion Rills		V					