CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	1 1				
Station:	Kincaid		Date:	01/29/25	
Impoundment Name:	Ash Pond	•	Time:	1:00 PM	
IEPA Number:	W0218140002-01		Inspector(s):	1). Hubur	
Sky: Sunny Temp.:	45015	Precip. (last 48 hrs):	0.00	Pool Elev.:	-6.0"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach

additional sheets as necessary. Circle General Condition for each section.

ITEM			101 00	DESCRIPTION		ACTION			
		ES	NO			MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Condition	Condition:		Fair / Poor	Repairs:	Date:			
Cracking			\overline{V}						
Settlement			√					ļ	
Erosion Rills			✓						
Animal Burrows			√						
Misalignment			ν						
Vegetation (greater than 12")			<u>/</u>						
UPSTREAM EMBANKMENT	General Condition	on: (toog	/ Fair / Poor	Repairs:	Date:			
Cracking			V						
Sloughing / Bulging			V						
Seepage			V						
Sink Holes			1						
Animal Burrows			V						
Erosion Rills			√						
Slope Protection / Rip Rap			V						
Vegetation (greater than 12")									
DOWNSTREAM EMBANKMENT	General Condition	on: (Goog	/ Fair / Poor	Repairs:	Date:			
Cracking			V					,	
Sloughing / Bulging			V						
Seepage			V						
Sink Holes		Ì	V						
Sand Boils (indicate if flowing and color)			1			-	,		
Animal Burrows		\overline{Z}		MONTO	zing		V		
Erosion Rills			V						
Vegetation (greater than 12")			1						
	General Condition	on: ((000)	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide dep	oth)		И						
Obstructions Present			4						
Seepage			V			<u> </u>			
Sand Boils (indicate if flowing and color)			V						
Erosion Rills			V						