CCR Impoundment Weekly Inspection

	CCN	impoundment weekly	inspection									
35 ILL. ADM. Code 845 / 40 CFR Part 257												
Station:	Kincaid		12/05/25									
Impoundment Name:	Ash Pond		Time: 1	2:08 PM								
IEPA Number:	W0218140002-0)1	Inspector(s): 1	. Hwork								
Sky: <u>Clausy</u> Temp.:	32°F	Precip. (last 48 hrs):	0.00"	Pool Elev.: -6.0								
"YES" responses require description (at the time of inspection. If "ACTION additional sheets as necessary. Circle	" selected is "INVESTI	GATE", please indicate date f										
				ACTION								
	7:			ATE .								

ITEM				DESCRIPTION			ACTION		
		ES	NO			MONITOR	INVESTIGATE	SENT TO DSM	
CREST G	eneral Conditi	on:/	Good	Fair / Poor	Repairs:	Date:			
Cracking		1	V,						
Settlement			V						
Erosion Rills			/						
Animal Burrows			/						
Misalignment			1						
Vegetation (greater than 12")			~						
UPSTREAM EMBANKMENT G	eneral Conditi	on:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			اج(er (name visco) Mont er er even water om 14 seem	SECTION SECTIO			
Sloughing / Bulging			V						
Seepage									
Sink Holes			/						
Animal Burrows			/						
Erosion Rills			V						
Slope Protection / Rip Rap			1						
Vegetation (greater than 12")			>						
DOWNSTREAM EMBANKMENT G	eneral Conditi	on:/	Good	/ Fair / Poor	Repairs:	Date:		**************************************	
Cracking		Ì	1						
Sloughing / Bulging			1						
Seepage			V						
Sink Holes			\						
Sand Boils (indicate if flowing and color)		/							
Animal Burrows			· .	MONTOR	119		V		
Erosion Rills			1		0				
Vegetation (greater than 12")			1						
SPILLWAY(S) G	eneral Conditi	on: (Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)			V						
Obstructions Present			V,						
Seepage			V.						
Sand Boils (indicate if flowing and color)			~						
Erosion Rills			V						