CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Kincaid		Date:	03/26/25
Impoundment Name:	Ash Pond	-	Time:	11:30 PM
IEPA Number:	W0218140002-01	-	Inspector(s):	1). Husen
Sky: Crousy Temp.:	55° F P	Precip. (last 48 hrs):	0.00	Pool Elev.: -16.0

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

				×	ACTION			
ITEM	YES	NO	DESCRIPTI	ON	MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Cond		Good	Fair / Poor Repairs:	Date:				
Cracking		V						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		N				10.1		
Vegetation (greater than 12")		1						
UPSTREAM EMBANKMENT General Cor	ndition:	Good	Fair / Poor Repairs:	Date:				
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Animal Burrows		V						
Erosion Rills		V						
Slope Protection / Rip Rap		1						
Vegetation (greater than 12")		V						
DOWNSTREAM EMBANKMENT General Con	ndition:	Good	Fair / Poor Repairs:	Date:				
Cracking		1						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		/						
Sand Boils (indicate if flowing and color)		/		7 P				
Animal Burrows	/							
Erosion Rills		V						
Vegetation (greater than 12")		1						
SPILLWAY(S) General Con	ndition:	6000	Fair / Poor Repairs:	Date:				
Actively Flowing (provide depth)		V						
Obstructions Present		V						
Seepage		/		A CONTRACTOR OF THE PROPERTY O				
Sand Boils (indicate if flowing and color)		V						
Erosion Rills		V		ALEBO AND THE STATE OF THE STAT				