CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	JJ (LLI)	Dittil Code 045 / 40 Cities are 255	1 1 -	
Station:	Kincaid	Date:	04/16/25	
Impoundment Name:	Ash Pond	Time:	0700	
IEPA Number:	W0218140002-01	Inspector(s):	1. Husur	•
Sky: CLGAN Temp.:	38° F 1	recip. (last 48 hrs): 0.00	Pool Elev.:	-9.0

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM			DESCRIPTION		ACTION			
		NO			MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Con	dition	Good	/ Fair / Poor Repairs:	Date:				
Cracking		V						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		X						
UPSTREAM EMBANKMENT General Con	dition:	Good	/ Fair / Poor Repairs:	Date:				
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V	,					
Animal Burrows		V	·					
Erosion Rills		√						
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")								
DOWNSTREAM EMBANKMENT General Con	dition:	Goog	/ Fair / Poor Repairs:	Date:				
Cracking		V						
Sloughing / Bulging		V						
Seepage		V			,			
Sink Holes		V						
Sand Boils (indicate if flowing and color)		V						
Animal Burrows	Ţ.,	V		,				
Erosion Rills	V		MONITORING		V			
Vegetation (greater than 12")			U					
SPILLWAY(S) General Con	dition:	Good	/ Fair / Poor Repairs:	Date:				
Actively Flowing (provide depth)		V						
Obstructions Present		V						
Seepage		1						
Sand Boils (indicate if flowing and color)		1						
Erosion Rills		V		,,				