			poundment Weekly Inspection			
35 ILL. ADM. Code 845 / 40 CFR Part 257 Station: Kincaid Date: のちしつ / 25						
Station:	Kincaid		Date: 05107	122	_	
Impoundment Name:	Ash Pond		Time: <i>l</i> ( ) / /		_	
IEPA Number:	W0218140002	:-01	Inspector(s): 1. Hub	run	_	
Sky: CLoudy Temp.:	72° F	. P	recip. (last 48 hrs): 0.00 Pool	Elev.:	-1	5 "
/ES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach diditional sheets as necessary. Circle General Condition for each section.						
				ACTION		
ITEM		NO	DESCRIPTION	TOR	TIGATE	70

Repairs:

Repairs:

Repairs:

Repairs:

MONITONIN

Date:

Date:

Date:

Date:

General Condition Good / Fair / Poor

V

 $\overline{V}$ 

7

V

 $\stackrel{\checkmark}{\sim}$ 

√

v

V

General Condition: Good / Fair / Poor

V

 $\overline{
u}$ 

マ

**CREST** 

Vegetation (greater than 12")

Slope Protection / Rip Rap

Vegetation (greater than 12")

Vegetation (greater than 12")
SPILLWAY(S)

**Obstructions Present** 

Actively Flowing (provide depth)

Sand Boils (indicate if flowing and color)

Sand Boils (indicate if flowing and color)

Sloughing / Bulging

Animal Burrows
Erosion Rills

UPSTREAM EMBANKMENT | General Condition: Good / Fair / Poor

DOWNSTREAM EMBANKMENT General Condition: Good/ Fair / Poor

Cracking Settlement

Erosion Rills
Animal Burrows

Misalignment

Sloughing / Bulging

Animal Burrows
Erosion Rills

Cracking

Seepage Sink Holes

Cracking

Seepage Sink Holes

Seepage

**Erosion Rills** 

SENT DSM