CCR Impoundment Weekly Inspection

	35 ILL.	ADM. Code 845 / 40	CFR Part 257	. 1
Station:	Kincaid		Date:	05/14/25
Impoundment Name:	Ash Pond		Time:	iPM
IEPA Number:	W0218140002-0	1	Inspector(s):	1). Husen
Sky: Paousy Temp.:	83°	Precip. (last 48 hrs):	0.16"	Pool Elev.: -18
ES" responses require description (the time of inspection. If "ACTION ditional sheets as necessary. Circle	" selected is "INVESTIG	ATE", please indicate date		onse indicates no issues were observed Safety Manager (DSM) . Attach
				ACTION

ITEM						A	ACTIO	N
		NO	DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM	
CREST Ge	eneral Condition	:(Goog	/ Fair / Poor	Repairs:	Date:			
Cracking		7						
Settlement		V			*1			
Erosion Rills		V						
Animal Burrows		~						
Misalignment		V						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT G	eneral Condition	: G000	/ Fair / Poor	Repairs:	Date:			
Cracking		Y						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Animal Burrows		V						
Erosion Rills		V			·			
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")		1						
DOWNSTREAM EMBANKMENT G	eneral Condition	Good	// Fair / Poor	Repairs:	Date:			
Cracking		V		-				
Sloughing / Bulging		~	,					
Seepage		V						
Sink Holes		V						
Sand Boils (indicate if flowing and color)		V	,					T
Animal Burrows			MONITO	niry				
Erosion Rills		ν						
Vegetation (greater than 12")		V		~				
	eneral Condition	: Zood	Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)		V						
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		1						
Erosion Rills		V						