CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

					1 -1	
Station:		Kincaid		Date:	05/28/25	
Impoundment Name:		Ash Pond	 ,	Time:	1300	
IEPA	Number:	W0218140002-0	01	Inspector(s):	D. Hwsur	
Sky: Crown	Temp.:	63° F	Precip. (last 48 hrs):	0.19"	Pool Elev.:	-14.0"

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM				DESCRIPTION		ACTION			
		YES	NO			MONITOR	INVESTIGATE	SENT TO DSM	
CREST Ge	neral Condi	tion:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			1					(au undetroitse	
Settlement			V						
Erosion Rills			V						
Animal Burrows			V						
Misalignment			V						
Vegetation (greater than 12")			X						
UPSTREAM EMBANKMENT Ge	neral Condi	tion:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			V		(Auto) and the second s				
Sloughing / Bulging			V						
Seepage			V						
Sink Holes			~		12				
Animal Burrows			V						
Erosion Rills			N						
Slope Protection / Rip Rap			N						
Vegetation (greater than 12")									
DOWNSTREAM EMBANKMENT Ge	neral Condi	tion:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			~						
Sloughing / Bulging			1						
Seepage			1						
Sink Holes			V						
Sand Boils (indicate if flowing and color)		,	V	A			,		
Animal Burrows		V		MONTTO	nry		V		
Erosion Rills			V,						
Vegetation (greater than 12")			V						
SPILLWAY(S) Ge	neral Condi	tion:		/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)			V						
Obstructions Present			V						
Seepage			1						
Sand Boils (indicate if flowing and color)			V						
Erosion Rills			1						