CCR Impoundment Weekly Inspection

		35 ILL.	ADM. Code 845 / 40	CFR Part 257	1 /25	
Station:		Kincaid	Date:		06 04 23	
Impoundment Name:		Ash Pond	_	Time:	130,0	
IEPA Number:		W0218140002-0	1	Inspector(s):	D. Husen	
Sky: RHIN	Temp.:	70°	Precip. (last 48 hrs):	0.46"	Pool Elev.:	-14,0
					ponse indicates no issues we n Safety Manager (DSM) . At	

additional sheets as necessary. Circle General Condition for each section.

ITEM						<i>P</i>	ACTIO	N
		ESNO	NO DESCRIPTION				INVESTIGATE	SENT TO DSM
CREST	General Condition	n: 6000	Fair / Poor	Repairs:	Date:			
Cracking		V						
Settlement		V						
Erosion Rills		V						
Animal Burrows		V						
Misalignment		V						
Vegetation (greater than 12")		V						
UPSTREAM EMBANKMENT	General Condition	n: (5 00)	/ Fair / Poor	Repairs:	Date:			
Cracking		V						
Sloughing / Bulging		V						
Seepage		V						
Sink Holes		V						
Animal Burrows		V						
Erosion Rills		V						
Slope Protection / Rip Rap		V						
Vegetation (greater than 12")		2						
DOWNSTREAM EMBANKMENT	General Condition	n: G00	/ Fair / Poor	Repairs:	Date:			
Cracking		V						
Sloughing / Bulging		~						
Seepage		V						
Sink Holes		V						
Sand Boils (indicate if flowing and color)		V	1.			/		
Animal Burrows		/	MONITO	ring		V		
Erosion Rills		V						
Vegetation (greater than 12")		V						
SPILLWAY(S)	General Condition	n: Goo	// Fair / Poor	Repairs:	Date:			
Actively Flowing (provide dep	oth)	V						
Obstructions Present		V						
Seepage		V						
Sand Boils (indicate if flowing and color)		1						
Erosion Rills		V						