CCR Impoundment Weekly Inspection

| | 35 ILL. / | ADIVI. Code 845 / 40 | CFR Part 257 | 1 100 |
|---|------------------|------------------------|---------------|--|
| Station | : Kincaid | | Date: | 06/11/25 |
| Impoundment Name | : Ash Pond | _ | Time: | 10:00 AM |
| IEPA Number | : W0218140002-01 | | Inspector(s): | D. Husur |
| Sky: Suny Temp. | 78° | Precip. (last 48 hrs): | 6.00 | Pool Elev.: -12.0 |
| ES" responses require description the time of inspection. If "ACTIO | | | | oonse indicates no issues were observed n Safety Manager (DSM) . Attach |

additional sheets as necessary. Circle General Condition for each section.

| ITEM | | | | | ACTION | | | |
|--|---------|------|------------------------------|---------|-------------|----------------|--|--|
| | | NO | DESCRIPTION | MONITOR | INVESTIGATE | SENT TO DSM | | |
| CREST General Cond | dition: | Good | / Fair / Poor Repairs: Date: | | | | | |
| Cracking | | V | | | | | | |
| Settlement | | V | | | | | | |
| Erosion Rills | | V | | | | | | |
| Animal Burrows | | V | | | | | | |
| Misalignment | | V | | | | | | |
| Vegetation (greater than 12") | | X | | | | | | |
| UPSTREAM EMBANKMENT General Cond | dition: | Good | / Fair / Poor Repairs: Date: | | | | | |
| Cracking | | V | | | | | | |
| Sloughing / Bulging | | V | | | | | | |
| Seepage | | V | | | | | | |
| Sink Holes | | V | | | | | | |
| Animal Burrows | | V | | | | | | |
| Erosion Rills | | V | | | | | | |
| Slope Protection / Rip Rap | | V | | | | | | |
| Vegetation (greater than 12") | | X | | | | | | |
| DOWNSTREAM EMBANKMENT General Condi | | Good | / Fair / Poor Repairs: Date: | | | | | |
| Cracking | | V | | | | | | |
| Sloughing / Bulging | | V | | | | | | |
| Seepage | | V | | | | | | |
| Sink Holes | | / | | | | | | |
| Sand Boils (indicate if flowing and color) | | V | ./ | / | | | | |
| Animal Burrows | | | MONITONING | | | | | |
| Erosion Rills | | V | U | | | | | |
| Vegetation (greater than 12") | | V | | | | 120 | | |
| SPILLWAY(S) General Cond | dition: | Good | Fair / Poor Repairs: Date: | | | | | |
| Actively Flowing (provide depth) | | V | | | | | | |
| Obstructions Present | | V | | | | | | |
| Seepage | | V | ** | | | | | |
| Sand Boils (indicate if flowing and color) | | 1 | | | | | | |
| Erosion Rills | | V | | | | | | |