## **CCR Impoundment Weekly Inspection** 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Newton	Date:	12/28/2021
Impoundment Name:	Primarry Ash Pond	Time:	9:35 AM
IEPA Number:	W0780700001-01	Inspector(s):	Terry Hanratty

Precip. (last 48 hrs):

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach ral Condition fo

Pool Elev.:

535.5

30

Temp.:

Sky: Clear

additional sheets as necessary. Circle Gene	ral Condition	for ea	ach section.			1		
ITEM							ACTIO	N
		NO	DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM	
CREST Gener	al Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		Χ						
Settlement		Χ						
Erosion Rills		Χ						
Animal Burrows		Χ						
Misalignment		Χ						
Vegetation (greater than 12")		Χ						
UPSTREAM EMBANKMENT Gener	al Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		Χ						
Sloughing / Bulging			Minor slogh	ing on south side-co	ontinuing to monitor	Χ		
Seepage		Χ						
Sink Holes		Χ						
Animal Burrows		Χ						
Erosion Rills		Χ						
Slope Protection / Rip Rap		Χ						
Vegetation (greater than 12")		Х		-				
DOWNSTREAM EMBANKMENT Gener	al Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		Χ						
Sloughing / Bulging		Χ						
Seepage		Χ						
Sink Holes		Χ						
Sand Boils (indicate if flowing and color)		Χ						
Animal Burrows		Χ						
Erosion Rills		Х						
Vegetation (greater than 12")		Х						
SPILLWAY(S) Gener	al Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)		Χ						
Obstructions Present		Χ						
Seepage		Χ						
Sand Boils (indicate if flowing and color)		Χ						
Erosion Rills		Χ						