CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Newton	Date:	2/16/2022
Impoundment Name:	Primarry Ash Pond	Time:	9:30 AM
IEPA Number:	W0780700001-01	Inspector(s):	Terry Hanratty
•		•	

Precip. (last 48 hrs):

Sky: Cloudy

Temp.: 47

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

Pool Elev.: 535.5

ACTION NVESTIGATE MONITOR **ITEM** YES NO **DESCRIPTION** SENT TO DSM **CREST** General Condition: Good / Fair / Poor Repairs: Date: Cracking Х Χ Settlement **Erosion Rills** Χ Χ **Animal Burrows** Χ Misalignment Vegetation (greater than 12") Χ **UPSTREAM EMBANKMENT** General Condition: Good / Fair / Poor Repairs: Date: Cracking Χ Sloughing / Bulging Minor sloghing on south side-continuing to monitor Χ Seepage Χ Sink Holes **Animal Burrows** Χ Χ **Erosion Rills** Slope Protection / Rip Rap Vegetation (greater than 12") **DOWNSTREAM EMBANKMENT** General Condition: Good / Fair / Poor Repairs: Date: Cracking Χ Sloughing / Bulging Χ Χ Seepage Х Sink Holes Χ Sand Boils (indicate if flowing and color) **Animal Burrows** Χ **Erosion Rills** Χ Х Vegetation (greater than 12") SPILLWAY(S) General Condition: Good / Fair / Poor Repairs: Date: Actively Flowing (provide depth) Χ **Obstructions Present** Χ Χ Seepage Χ Sand Boils (indicate if flowing and color) **Erosion Rills**