CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Newton	Date:	5/4/2022		
Impoundment Name:	Primarry Ash Pond	Time:	10:30 AM		
IEPA Number:	W0780700001-01	Inspector(s):	Terry Hanratty		
<u>'</u>					

Precip. (last 48 hrs):

Sky: Cloudy

Temp.:

60

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

0.3"

Pool Elev.:

536

ITEM							-	ACTIO	N
		YES	NO	DESCRIPTION		N	MONITOR	INVESTIGATE	SENT TO DSM
CREST	General Condi	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Settlement			Х						
Erosion Rills			Х						
Animal Burrows			Х						
Misalignment			Х						
Vegetation (greater than 12")	Vegetation (greater than 12")		Х						
UPSTREAM EMBANKMENT	General Condi	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Sloughing / Bulging		Χ		Minor sloghing	on south side-continuing to monitor		Χ		
Seepage			Х						
Sink Holes			Х						
Animal Burrows			Х						
Erosion Rills			Х						
Slope Protection / Rip Rap			Х						
Vegetation (greater than 12")			Х						
DOWNSTREAM EMBANKMENT	General Condi	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Х						
Sloughing / Bulging			Х						
Seepage			Х						
Sink Holes			Х						
Sand Boils (indicate if flowing and color)			Х						
Animal Burrows			Х						
Erosion Rills			Χ						
Vegetation (greater than 12")			Х						
SPILLWAY(S)	General Condi	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)			Χ						
Obstructions Present			Χ						
Seepage			Χ						
Sand Boils (indicate if flowing and color)			Χ						
Erosion Rills			Х						