CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

| Station: Newton | | | 1 | Date: | 5/10/2022 | |
|-----------------------------|-------------------------------------|----|------------------------|---------------|----------------|-----|
| Impou | Impoundment Name: Primarry Ash Pond | | | Time: | 10:30 AM | |
| IEPA Number: W0780700001-01 | | | 01-01 | Inspector(s): | Terry Hanratty | |
| Sky: Clear | Temp.: | 68 | Precip. (last 48 hrs): | 0 | Pool Elev.: | 536 |

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

| ITEM | | YES | NO | DESCRIPTION | | ACTION | | |
|--|---------------|--------|------|--|---|-------------|----------------|--|
| | | | | | | INVESTIGATE | SENT TO DSM | |
| CREST | General Condi | ition: | Good | / Fair / Poor Repairs: Date: | | | | |
| Cracking | | | Х | | | | | |
| Settlement | | | Х | | | | | |
| Erosion Rills | | | Х | | | | | |
| Animal Burrows | | | Х | | | | | |
| Misalignment | | | Х | | | | | |
| Vegetation (greater than 12") | | Х | | Scheduled to mow June 13th | | | | |
| UPSTREAM EMBANKMENT General Condition: Good / Fair / Poor Repairs: Date: | | | | | | | | |
| Cracking | | | Х | | | | | |
| Sloughing / Bulging | | Х | | Minor sloghing on south side-continuing to monitor | Х | | | |
| Seepage | | | Х | | | | | |
| Sink Holes | | | Х | | | | | |
| Animal Burrows | | | Х | | | | | |
| Erosion Rills | | | Х | | | | | |
| Slope Protection / Rip Rap | | | Х | | | | | |
| Vegetation (greater than 12") | | Х | | Scheduled to mow June 13th | | | | |
| DOWNSTREAM EMBANKMENT | General Condi | ition: | Good | / Fair / Poor Repairs: Date: | | | | |
| Cracking | | | Х | | | | | |
| Sloughing / Bulging | | | Х | | | | | |
| Seepage | | | Х | | | | | |
| Sink Holes | | | Х | | | | | |
| Sand Boils (indicate if flowing and color) | | | Х | | | | | |
| Animal Burrows | | | Х | | | | | |
| Erosion Rills | | | Х | | | | | |
| Vegetation (greater than 12") | | Х | | Scheduled to mow June 13th | | | | |
| SPILLWAY(S) | General Condi | ition: | Good | / Fair / Poor Repairs: Date: | | | | |
| Actively Flowing (provide depth) | | | Х | | | | | |
| Obstructions Present | | | Х | | | | | |
| Seepage | | | Х | | | | | |
| Sand Boils (indicate if flowing and color) | | | Х | | | | | |
| Erosion Rills | | | Х | | | | | |