CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Newton	Date:	6/8/2022
Impoundment Name:	Primarry Ash Pond	Time:	9:25 AM
IEPA Number:	W0780700001-01	Inspector(s):	Terry Hanratty
		_	

Precip. (last 48 hrs):

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach

0

Pool Elev.:

536

additional sheets as necessary. Circle General Condition for each section.

72

Temp.:

Sky: Cloudy

ITEM					ACTION			
		NO		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM
CREST Genera	l Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		Χ						
Settlement		Х						
Erosion Rills		Х						
Animal Burrows		Х						
Misalignment		Х						
Vegetation (greater than 12")			Scheduled to mow June 13th					
UPSTREAM EMBANKMENT General	l Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking		Х						
Sloughing / Bulging			Minor sloghing	g on south side-c	ontinuing to monitor	Χ		
Seepage		Х						
Sink Holes		Х						
Animal Burrows		Х						
Erosion Rills		Х						
Slope Protection / Rip Rap		Х						
Vegetation (greater than 12")			Scheduled to mow June 13th					
DOWNSTREAM EMBANKMENT General Cond		Good	/ Fair / Poor	Repairs:	Date:			
Cracking		Х						
Sloughing / Bulging		Х						
Seepage		Х						
Sink Holes		Х						
Sand Boils (indicate if flowing and color)		Х						
Animal Burrows		Х						
Erosion Rills		Х						
Vegetation (greater than 12")			Sch	eduled to mow l	June 13th			
SPILLWAY(S) General	l Condition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)		Χ						
Obstructions Present		Χ						
Seepage		Χ						
Sand Boils (indicate if flowing and color)		Χ						
Erosion Rills		Χ						