CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	Station:	Newtor	1	Date:	6/22/2022	
Impoundment Name: Primarry Ash Pond			Pond	Time:	1:00 PM	
IEPA Number: W0780700001-01			01-01	Inspector(s):	Terry Hanratty	
Sky: Clear	Temp.:	96	Precip. (last 48 hrs):	0	Pool Elev.:	536

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM						ACTION		
		YES	NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Cond	ition:	Good	/ Fair / Poor Repairs: Date:				
Cracking			Х					
Settlement			Х					
Erosion Rills			Х					
Animal Burrows			Х					
Misalignment			Х					
Vegetation (greater than 12")		Х		Scheduled to mow June 13th				
UPSTREAM EMBANKMENT General Condition: Good / Fair / Poor Repairs: Date:								
Cracking			Х					
Sloughing / Bulging		Х		Minor sloghing on south side-continuing to monitor	Х			
Seepage			Х					
Sink Holes			Х					
Animal Burrows			Х					
Erosion Rills			Х					
Slope Protection / Rip Rap			Х					
Vegetation (greater than 12")		Х		Scheduled to mow June 13th				
DOWNSTREAM EMBANKMENT General Condition				/ Fair / Poor Repairs: Date:				
Cracking			Х					
Sloughing / Bulging			Х					
Seepage			Х					
Sink Holes			Х					
Sand Boils (indicate if flowing and color)			Х					
Animal Burrows			Х					
Erosion Rills			Х					
Vegetation (greater than 12")		Х		Scheduled to mow June 13th				
SPILLWAY(S)	General Cond	ition:	Good	/ Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)			Х					
Obstructions Present			Х					
Seepage			Х					
Sand Boils (indicate if flowing and color)			Х					
Erosion Rills			Х					