CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:		Newtor	1	Date:	7/13/2022	
Impoundment Name:		Primarry Ash Pond		Time:	7:30 AM	
	IEPA Number:	W0780700001-01		Inspector(s):	Terry Hanratty	
Sky: Clear	Temp.:	72	Precip. (last 48 hrs):	0	Pool Elev.:	536

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach

additional sheets as necessary. Circle General Condition for each section.

ITEM					ACTION		
		NO	DESCRIPTION	MONITOR	INVESTIGATE	SENT TO DSM	
CREST General Con	dition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		Х					
Settlement		Х					
Erosion Rills		Х					
Animal Burrows		Х					
Misalignment		Х					
Vegetation (greater than 12")		Х	Blankenship mowed 6/27/22				
UPSTREAM EMBANKMENT General Con	dition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		Х					
Sloughing / Bulging			Minor sloghing on south side-continuing to monitor	Х			
Seepage		Х					
Sink Holes		Х					
Animal Burrows		Х					
Erosion Rills		Х					
Slope Protection / Rip Rap		Χ					
Vegetation (greater than 12")		Х	Blankenship mowed 6/27/22				
DOWNSTREAM EMBANKMENT General Con	dition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		Х					
Sloughing / Bulging		Х					
Seepage		Х					
Sink Holes		Х					
Sand Boils (indicate if flowing and color)		Х					
Animal Burrows		Х					
Erosion Rills		Х					
Vegetation (greater than 12")			Scheduled to mow June 13th				
SPILLWAY(S) General Con	dition:	Good	/ Fair / Poor Repairs: Date:				
Actively Flowing (provide depth)		Χ					
Obstructions Present		Х					
Seepage		Х					
Sand Boils (indicate if flowing and color)		Х					
Erosion Rills		Х					