## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Newton	Date: _	11/2/2022
Impoundment Name:	Primarry Ash Pond	Time:	9:30 AM
IEPA Number:	W0780700001-01	Inspector(s):	Terry Hanratty

Precip. (last 48 hrs):

Sky: Clear

Temp.:

55

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

Pool Elev.:

536

ITEM								ACTIO	N
		YES	NO	DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Condit	ion:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Settlement			Χ						
Erosion Rills			Χ						
Animal Burrows			Χ						
Misalignment			Χ						
Vegetation (greater than 12")			Χ	Blankenship mowed ash pond berms 8/22/22					
UPSTREAM EMBANKMENT	General Condit	ion:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Sloughing / Bulging		Χ		Minor sloghing	linor sloghing on south side-continuing to monitor		Χ		
Seepage			X						
Sink Holes			Χ						
Animal Burrows			Χ						
Erosion Rills			Χ						
Slope Protection / Rip Rap			Χ						
Vegetation (greater than 12")			Χ	Blankenship mowed ash pond berms 8/22/22					
DOWNSTREAM EMBANKMENT	General Condit	ion:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Sloughing / Bulging			Χ						
Seepage			Х						
Sink Holes			Х						
Sand Boils (indicate if flowing and color)			Χ						
Animal Burrows			Χ						
Erosion Rills			Χ						
Vegetation (greater than 12")			Χ	Blankenship mowed ash pond berms 8/22/22					
SPILLWAY(S)	General Condit	ion:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide de	pth)		Χ						
Obstructions Present			Χ						
Seepage			Χ						
Sand Boils (indicate if flowing and color)			Χ						
Erosion Rills			Χ						