CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	Station:	Newton		Date:	2/22/2023	
Impoun	dment Name:	Primarry Ash	Pond	Time:	9:18 AM	
1	IEPA Number:	W078070000	1-01	Inspector(s):	Terry Hanratty	
lar Claudy	Tomn	E0	Dracin (last 48 bys):	0	Pool Floy	E2E

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM						ACTION			
		YES N		DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM	
CREST	General Condi	tion:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Settlement			Χ						
Erosion Rills			Χ						
Animal Burrows			Χ						
Misalignment			Χ						
Vegetation (greater than 12")			Χ						
UPSTREAM EMBANKMENT	General Condi	tion:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Sloughing / Bulging		Χ		Minor slogh	ing on south side-co	ontinuing to monitor	Χ		
Seepage			Χ						
Sink Holes			Χ						
Animal Burrows			Χ						
Erosion Rills			Χ						
Slope Protection / Rip Rap			Χ						
Vegetation (greater than 12")			Χ						
DOWNSTREAM EMBANKMENT	General Condi	tion:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Χ						
Sloughing / Bulging			Χ						
Seepage			Х						
Sink Holes			Х						
Sand Boils (indicate if flowing and color)			Χ						
Animal Burrows			Χ						
Erosion Rills				l erosion on ac	cess roads to lake p	ump and west side of	á		
Vegetation (greater than 12")			Χ						
SPILLWAY(S)	General Condi	tion:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)			Χ	R	emoved 1 stop log :	11/16/22			
Obstructions Present			Χ						
Seepage			Χ						
Sand Boils (indicate if flowing and color)			Χ						
Erosion Rills			Χ						