## CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

	Station:	Newton		Date:	7/5/2023	
Impoundm	ent Name:	Primarry Ash	Pond	<b>Time:</b> 11:50 AN		
IEPA Number:		W078070000	01-01	Inspector(s):	Terry Hanratty	
Sky: Clear	Temp.:	87	Precip. (last 48 hrs):	0.3"	Pool Elev.:	534.5

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM						4	ACTION		
		YES	NO		DESCRIPTIO	CRIPTION		INVESTIGATE	SENT TO DSM
CREST	General Condi	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Х						
Settlement			Х						
Erosion Rills			Х						
Animal Burrows			Х						
Misalignment			Х						
Vegetation (greater than 12")			Х	Blanker	nship mowed wee	k of June 19th			
UPSTREAM EMBANKMENT	General Condi	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Х						
Sloughing / Bulging		Х		Minor sloghin	g on south side-co	ontinuing to monitor	Х		
Seepage			Х						
Sink Holes			Х						
Animal Burrows			Х						
Erosion Rills			Х						
Slope Protection / Rip Rap			Х						
Vegetation (greater than 12")			Х	Blanker	nship mowed wee	k of June 19th			
DOWNSTREAM EMBANKMENT	General Condi	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Cracking			Х						
Sloughing / Bulging			Х						
Seepage			Х						
Sink Holes			Х						
Sand Boils (indicate if flowing and color)			Х						
Animal Burrows			Х						
Erosion Rills			Х						
Vegetation (greater than 12")			Х	Blanker	nship mowed wee	k of June 19th			
SPILLWAY(S)	General Condi	ition:	Good	/ Fair / Poor	Repairs:	Date:			
Actively Flowing (provide depth)			Х	Re	moved 1 stop log	11/16/22			
Obstructions Present			Х						
Seepage			Х						
Sand Boils (indicate if flowing and color)			Х						
Erosion Rills			Х						