CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Newton	Date:	8/30/2023
Impoundment Name:	Primarry Ash Pond	Time:	11:00 AM
IEPA Number:	W0780700001-01	Inspector(s):	Terry Hanratty
		-	

Precip. (last 48 hrs):

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

0

Pool Elev.:

534.5

75

Temp.:

Sky: Clear

additional sheets as necessary. Circle General Conc		101 00			ACTION		
		NO			MONITOR	INVESTIGATE	SENT TO DSM
CREST Gene	eral Condition:	Good	Fair / Poor Repairs:	Date:			
Cracking		Χ					
Settlement		Х					
Erosion Rills		Х					
Animal Burrows		Х					
Misalignment		Х					
Vegetation (greater than 12")		Х	Blankenship mowing this week of	August 28th.			
UPSTREAM EMBANKMENT Gene	ral Condition:	Good	Fair / Poor Repairs:	Date:			
Cracking		Х					
Sloughing / Bulging			Minor sloghing on south side-contin	on south side-continuing to monitor			
Seepage		Х					
Sink Holes		Х					
Animal Burrows		Х					
Erosion Rills		Х					
Slope Protection / Rip Rap		Х					
Vegetation (greater than 12")		Х	Blankenship mowing this week of August 28th.				
DOWNSTREAM EMBANKMENT Gene	ral Condition:	Good	Fair / Poor Repairs:	Date:			
Cracking		Х					
Sloughing / Bulging		Х					
Seepage		Х					
Sink Holes		Х					
Sand Boils (indicate if flowing and color)		Х					
Animal Burrows		Х					
Erosion Rills		Х					
Vegetation (greater than 12")		Χ	Blankenship mowing this week of	August 28th.			
SPILLWAY(S) Gene	ral Condition:	Good	Fair / Poor Repairs:	Date:			
Actively Flowing (provide depth)		Χ	Removed 1 stop log 11/1	6/22			
Obstructions Present		Χ					
Seepage		Χ					
Sand Boils (indicate if flowing and color)		Χ					
Erosion Rills		Χ					