CCR Impoundment Weekly Inspection 35 ILL. ADM. Code 845 / 40 CFR Part 257

Station:	Newton	Date:	11/22/2023
Impoundment Name:	Primarry Ash Pond	Time:	7:10 AM
IEPA Number:	W0780700001-01	Inspector(s):	Terry Hanratty

Sky: Cloudy	Temp.:	37	Precip. (last 48 hrs):	0.1"	Pool Elev.:	534.5

"YES" responses require description (size, depth, extents, color) and location in "DESCRIPTION" section. "NO" response indicates no issues were observed at the time of inspection. If "ACTION" selected is "INVESTIGATE", please indicate date forwarded via email to Dam Safety Manager (DSM). Attach additional sheets as necessary. Circle General Condition for each section.

ITEM					ACTION		
		ES NO DESCRIPTION		MONITOR	INVESTIGATE	SENT TO DSM	
CREST Gen	eral Condition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		Х					
Settlement		Х					
Erosion Rills		Х					
Animal Burrows		Х					
Misalignment		Х					
Vegetation (greater than 12")		Х	Blankenship mowing this week of August 28th.				
UPSTREAM EMBANKMENT Gen	eral Condition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		Х					
Sloughing / Bulging	Х		Minor sloghing on south side-continuing to monitor	Χ			
Seepage		Х					
Sink Holes		Х					
Animal Burrows		Х					
Erosion Rills		Х					
Slope Protection / Rip Rap		Х					
Vegetation (greater than 12")		Х	Blankenship mowing this week of August 28th.				
DOWNSTREAM EMBANKMENT Gen	eral Condition:	Good	/ Fair / Poor Repairs: Date:				
Cracking		Х					
Sloughing / Bulging		Х					
Seepage		Х					
Sink Holes		Х					
Sand Boils (indicate if flowing and color)		Х					
Animal Burrows		Х					
Erosion Rills		Х					
Vegetation (greater than 12")		Х	Blankenship mowing this week of August 28th.				
` ,	eral Condition:		· ·				
Actively Flowing (provide depth)		Х	Removed 1 stop log 11/16/22				
Obstructions Present		Х					
Seepage		Х					
Sand Boils (indicate if flowing and color)		Х					
Erosion Rills		Χ					